

NW Training Integration Study Team Minutes
1 March 2001
Meeting held via Telephone Conference call

1. IMF advised that the updated matrix had been received from PSNS, and that the requested lesson plans had been mailed to PSNS. PSNS has not received yet.
2. After a short discussion it was agreed that Sheetmetal workers being loaned to IMF from PSNS do not require the HAZMAT Originator Qualifications.
3. IMF still has not obtained a sample workmanship test for PSNS to review. After a short discussion, it was recommended that the welders being loaned to PSNS from IMF receive a four hour class on workmanship and that PSNS welders being loaned to IMF from PSNS be advised that they are not authorized to sign off their own work at IMF. An IMF QA representative will be required to sign off the work. IMF will check with their Hull division and advise the team of the decision at the next meeting.
4. 8259 CD, IMF requested a copy of this PSNS CD each time it is updated, PSNS will investigate and advise at the next meeting.
5. PSNS advised that there were several courses available on CD now, IMF requested copies for review of Sub-Safe and HAZMAT.
6. It was noted that IMF has a two day course required for painters that cover corrosion control and general safety of ships. PSNS asked for IMF to advise what they cover and are they a hard requirement.
7. After a short discussion IMF and PSNS agreed that ladders loaned from PSNS to IMF were not all required to have "R" qualifications. IMF will identify which borrows require this qualification at the time of borrow.
8. The next meeting will be held on 8 March 2001 via telephone conference call

ATTENDEES:

1.

<u>NAME</u>	<u>COMMAND</u>	<u>PHONE</u>	<u>E-MAIL</u>
S. Bence	IMFB	315-1804	susan.bence@imfb.navy.mil
V. Rutter	PSNS	476-4622	ruttervern@psns.navy.mil
C. Papillion	IMFB	315-1847	cherron.papillion@imfb.navy.mil
W. Petty	NWRMC	476-0105	petty@rmca.pnwrmc.navy.mil
L. Malhoit	PSNS	476-4527	malhirotl@psns.navy.mil
B. Muhleman	PSNS	476-1193	muhlemanr@psns.navy.mil